








10 X Fischer plugs FU 8X50  
10 X SCREWS FOR CHIPBOARD 6X50




6 X Zebra plugs 6x37  
6 X SCREWS FOR CHIPBOARD 4x50





16 X Zebra plugs 6x37  
16 x snap caps for screws  
16 X SCREWS FOR CHIPBOARD 4x50















3 X Zebra plugs 6x37  
 3 X SCREWS FOR CHIPBOARD 4x50




14 X Zebra plugs 6x37  
 14 X SCREWS FOR CHIPBOARD 4x50









X 2




L > 2M




Fixation des consoles de coulissement haute




Fixation des consoles de coulissement basse




Fixation des consoles de coulissement haute









① ↑



② →



① ↑



② →

